



## WIPES, CLOGS AND MORE RAGS

Are Lift Station Ragging Issues **Consuming** Your Maintenance Efforts?

This Issue Is More And More Common... It's Not Going Away!

Let DAPARAK & AQUALITEC Provide A Cost Effective Solution!

Cost Saving, Labor Saving **SOLUTION** To CLOGS

AQUALITEC'S SCREENTEC **Removes & Eliminates** The Problem

SCREENTEC Does NOT Pass The Issue To Cause Failures Downstream

Rags & Debris Are **Automatically** Eliminated: Saving Time & Equipment

Typical Maintenance Costs For First 3 Years: Average \$0

## NO RE-DESIGN OR RE-ENGINEERING BUDGETED? NO PROBLEM!

### SCREENTEC

#### Is Designed;

to Retrofit Existing Stations  
via Existing Configuration  
for Ease Of Installation


#### With Flexibility;

of Materials & Selections  
via Control Scheme  
to Meet Process Flow Needs  
for Site Specific Demands

#### To Perform!



### Proven Performance! Case Studies Available Upon Request



## AQUALITEC'S SCREENTEC

### DESIGN FEATURES AND BENEFITS

- Can Easily Be Installed Onsite By Your Maintenance Crew
- Configurable, Modular Design Will Meet Any Challenge
- Vertical Design = Retrofits up to 50' With Minimal or NO Modifications
- Configurable, Modular Design Will Meet Any Challenge
- Odor Control; Completely Enclosed Frame & Washer-compactor With A Bagger




### PERFORMANCE

- Automatic Vertical Bar Screen: Intervals User Configured
- Industrial & Municipal Applications
- Flow Capacities: Up To 60MGD
- Configurable Screening: Bar Openings From 3/8" to 2"

### SAFER, BY DESIGN

- Any Maintenance Is Outside The Wetwell, Simple Design
- No Moving Parts Below Grade
- No Confined Space Entry Needed For Wear items



Aqualitec  
Video  
Directory

The Above Was Installed By The End User's  
Maintenance Crew.  
No Additional Engineering, Design, or  
Major Structural Modification Was Needed.

Aqualitec  
SCREENTEC  
Video



**Proven Performance! Case Studies Available Upon Request**